

Wheatland-Chili CSD

March Update 2015



Nurse's Office

Complete accessories – soap and cup dispenser



Server Room

Removed door and frame. Infilled door with CMU. This side covered with pegboard.



Art Room

Cleaned and waxed.



Art Room

Lighting complete.



Art Room

Shades installed.



Art Room Storage

All cabinets and shelving installed.



Fitness Room

Equipment moved.



Fitness Room

Base complete.